



495-0003-00 Rev R SW, GEN3, CONFIGURATION UTILITY (Build 1.2.3)

## CHANGES IN THIS RELEASE

- Fixed issue where slight amount of sidetone is reflected back to headset in intercom mode

## CHANGED FIRMWARE

Model	FW P/N	FW Rev.	Description
SON150_V2	490-4097-00	3	FW, SON150.V2, BASE STATION, 5-USER,PORT-XFMR,GEN 3.9
SON150B_V2	490-4098-00	3	FW, SON150B.V2, INTERCOM ON RADIO, GEN 3.9